Oil Field Environmental Incident Summary

Responsible Party: Triangle USA Petroleum Corporation

Well Operator: TRIANGLE USA PETROLEUM CORPORATION

Well Name: BRITT CENTRAL TANK BATTERY

Field Name: ELK Well File #:

 Date Incident:
 1/27/2015
 Time Incident:
 06:00
 Facility ID Number:
 228511-01

 County:
 MCKENZIE
 Twp:
 151
 Rng:
 102
 Sec:
 4
 Qtr:
 LO T3

Location Description:

Submitted By: Brittany Vannoy Received By:

Contact Person: Brittany Vannoy

1200 17TH ST., SUITE 2600 DENVER, CO 80202-5826

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Vessel Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 20 Barrels

Description of Other Released Contaminant:

Fresh Water

Inspected: Written Report Received: 3/7/2016 Clean Up Concluded: 1/27/2015

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts: None	
Action Taken or Planned: The ice will be melted/standing liquid will be sucked up and sent to disposal.	
Wastes Disposal Location:	
Agencies Involved:	

Updates

Date: 1/29/2015 Status: Reviewed - Assigned to Other Agency Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.